

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Certificate

Patent Number:

6,968,830 B2

FEB 2 8 2006

Issued:

November 29, 2005

of Correction

Name of Patentee:

Glenn et al.

Title of Invention:

Apparatus And Method For Suppressing Internal Combustion Ignition

Engine Emissions

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. § 1.322(a))

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

ATTENTION:

Decision and Certificate of Correction

Branch of the Patent Issue Division

Sirs:

It is noted that an error appears in this patent of a typographical nature or character, as more fully described below. The mistake incurred through the fault of the Patent and Trademark Office. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.

I certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on

(Date of Deposit)

Maria M. Thomson
(Name of Person Mailing Paper)

Maria M. Momson 2/16

Enlature Date

The errors appear in the body of the patent: column 8, line 14.

Please send the Certificate of Correction to:
Cantor Colburn LLP
55 Griffin Road South

55 Griffin Road South Bloomfield, Connecticut 06002

Patentees believe that no fee is due; however, if there are any additional charges with respect to this request or otherwise, please charge them to Deposit Account No. 06-1130 maintained by Patentees' attorneys.

Respectfully submitted,

CANTOR COLBURN LLP

Bv:

David A. Fox

Registration No. 38,807 55 Griffin Road South

Bloomfield, Connecticut 06002

Telephone: (860) 286-2929 Customer No.: 023413

Date: February 14, 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,968,830 B2

DATED: November 29, 2005

INVENTOR(S): Glenn et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8:

Line 14, after "about" delete "3" and insert therefor -- 10 --

MAILING ADDRESS OF SENDER: Cantor Colburn LLP 55 Griffin Road South Bloomfield CT 06002 PATENT NO. ___6,968,830 B2

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.